

TECHNICAL SERVICE BULLETIN

NO. 73-C-1



Austin MG

May, 1973

SUBJECT:

VYBACK REAR WINDOWS

MODELS:

ALL CONVERTIBLES

The Vyback rear window on convertible tops sometimes becomes badly creased due to incorrect stowage of the soft top assembly. We have found that these creases in most cases can be removed satisfactorily by simply filling a plastic bottle with hot water and rolling it across the creased area and at the same time supporting the opposite side of the window.

J.P.