



Austin MG

August, 1977

SUBJECT: COOLING FAN THERMAL CUT-OUT INSTALLATION

MODELS: 1977 MGB


As a courtesy service to all owners of 1977 MGBs we would ask that during pre-delivery or at the next convenient service, the in-line fuse which controls the cooling fans be removed and replaced with a thermal cut-out which is available under part #BLM 601018.

This thermal cut-out has a maximum rating of 20 amps and is self-healing, in the unlikely event that an overload condition should occur.

The in-line fuse is located on the right inner valance of the car, underneath the fuse block, has a green lead on one side and a white with brown tracer on the other. The diagram below indicates the correct location of the thermal cut-out.

Warranty claims may be submitted for this modification as follows: Thermal Cut-Out kit - part #BLM 601018 - Warranty time allowance will be 0.30 hours.

20 Amp Thermal Cut-Out Switch



J.P.