

TECHNICAL SERVICE BULLETIN

77-B-4

NO.



Austin MG

June, 1977

SUBJECT: SERVICING OF ELECTRONIC MODULES FOR IN-BUILT ELECTRONIC DISTRIBUTORS	MODELS: All
--	-----------------------

Listed below is the cross-reference information for electronic distributors, amplifiers and vacuum units fitted to 1977 models. This information is to be used in conjunction with the information and instructions contained in original bulletin #76-B-4.

<u>Vehicle</u>	<u>Dist.</u>	<u>Amplifier Vac. Assy.</u>	<u>Vacuum Unit</u>
MG Midget 1977 Federal	41697	54429790	54429788
MG Midget 1977 California	41698	54429455	54427198
MGB 1977 Federal	41693	54429706	54429339
MGB 1977 California	41695	54429700	54429697

Note: When using amplifier assembly 83475 (with vac unit blanked off) to replace the amplifier/vac unit assy. on early '76 MGBs (on which a vac unit was fitted but not connected) you will also require a new base plate 54427746 which will hold the pick-up in a fixed position.

It should also be noted that warranty replacement of the complete electronic distributor due to an amplifier failure is not acceptable unless amplifiers are unavailable through normal supply channels at the time of replacement.

JNLA